


CNCC/ Laser / Mechanical Engraving Machine Assembly Tutorial



Transmission coupling rod should have no significant movement




M3X12/2pcs ' Do not use excessive force



M3X35+spring/2pcs



Insert four small bearings, the bottom of the bearing flush with the bottom of plastic parts



M3X16/4PCS Do not use excessive force



M3X16/3PCS Pre-lock, temporarily do not lock




M3X12/2PCS Do not use excessive force






M3X35 + spring / 4PCS

Insert large bearings into the stay
Flush with the edge




M3X12/6PCS Do not tighten very hard, just sufficiently to secure the bearing






M3X14+3mm Nylon spacer / 4PCS





Note the orientation of the motor



Secure the coupling nut with grub screws














Move the spindle motor clamp close to the stepper motor



M3X16/4PCS Do not use great force











S

Note the direction of the motor and the board













Load the Z-axis module and note the direction of the plate






Do not lock the coupling and motor. Also, adjust the back



M5X14 + T nut / 4PCS pre-locking Do not lock







M5X8+T Nut / 4PCS pre-lock, do not lock



Place the aluminium profile on a flat surface (preferably a thick glass plane) to connect the two aluminium pieces









M5X14+T Nut / 3PCS pre-lock



M4X10/2PCS Do not lock, pay attention to pvc board slotted direction













M4X10/2PCS








Place the aluminium profile on a flat surface (preferably a thick glass plane)



M5X8 + T nuts


Not locked, needs to be adjusted later

This surface is not flat












Move the platform to this side and lock the coupling





Lock shaft seat and screw

Install the X module into the rack




M5X8+T Nut, lock the rack beam






M4X10/3pcs








Locking the shaft seat with the set screw

Move the X axis to this side, then lock the coupling







Insert the motor and then tighten the screws, do not use excessive force





The laser module is mounted as shown





M3X6+M3 Brass stand-off +M3T Nuts/3pcs











Congratulations on the completion of the installation of the engraving machine!

Please lubricate the lead-screws and sliders with oil!

Rotate the lead screws by hand. The shaft should rotate smoothly.

If necessary, please release the couplings for fine-tuning.

Finally, check all screws for tightness

After the completion of power test machine.

The provided software and tutorials require user self-learning °