



Screw terminal connects to ground and +16V from DC wall-wart

NB: this should be an Arduino MKR1000, not Nano. 3.7V battery connects via the 2-pin JST connector (not A6, and A7 as shown)  
Pin IDs rather than locations match the MKR1000

